

A-Ryung



A-Ryung markasına ait ürünlerin tedariğini paralel ithalat yöntemi ile gerçekleştirmekteyiz. İhtiyacınız olan A-Ryung ürünlerinin temini noktasında, bizimle iletişime geçebilirsiniz. Konusunda uzman satış personelimiz, ürünlere ait fiyat ve teslim sürelerini belirten teklifimiz ile, en kısa süre de size dönüş yapacaklardır. YALNIZCA ORJİNAL VE YENİ ÜRÜN SATIŞI YAPMAKTAYIZ. Firmamızın internet sitesinde gösterilen A-Ryung markasının yetkili distribütör veya üretici temsilcisi olmayıp, bu sitede gösterilen Özel marka adları ve ticari markalar ilgili sahiplerinin mülkiyetindedir.

Ürün listesi

Ürün	Tarif
08080818	
2119430	
5132240 ACP-1500HMFS70	
5132240 ACP-1500HMFS70	
5151430	
AR-99-00528	
AR-99-00097	
AHGP-700	
AMFP-X	
AMGP-01AF-T03-T-200	
AR-99-00056 A-RYUNG AMGP-01A-F	
AR-99-00065	
AR-99-00109 ACP1500	
AR-99-00126 ACP-1500 HMFS 70	
AR-99-00131	
AR-99-00132 ACP3700	
ASPK4 11/3 60HZ	
ASPK4 11/5	
ASPK4 11/8	
ASPK8 7/5	
ASPK8 7/7	
ASPK8 7/7 50HZ	
ASPK8 7/7 60HZ	
ASPKE4 11/5	
ATR-216HA(VB)	
AWS-NR.: 5132230	
AWS-NR.: 5135000	
PVO-30	
SHAFT FOR PUMP TYPE: ACRK-2-150/15, S/N: 07070862	
T.P.ACP-2200HMFS100	
ACRK4-100/5	
ACP-180F (5136340)	
ACP-3700 HMFS 115	
AMTP-212HA	

Urün	Tarif
AR-99-00281	
AR-99-03045	
ACP-1500 HMFS70 obsolete, replacement ACP-1800HMFS70	
ACP-1800HMFS70 (5161790)	
T- Rotor 220 HAVB	
ACP-3700HMFS145	
ACP-1800HMFS 70	
AR-99-00142	
2 HP (1.5KW) 4P alternativ 216 HWM + Mo 1500W	
ATP-216HA	
2VB-4L	
AR-99-00174	
INTERNAL DIA.240/THICKNESS 3	
ACP-900HMFS45 (5132260), obsolete replaced by T.P.ACP-1100HMFS45 30L/3Bar	
ARD-345 0.03 (cc/st)	
ARD-345 0.06 (cc/st)	
ARD-345 0.10 (cc/st) part name, the correct name ARD-345-33333	
AR-99-00062	
ACP-3700HMFS145/5132180	
ACP-2500HMFS100	
05010160	
5151430	
Motor for Type ACRK4-100/10, 2.2 kW, 100 L/min	
Impeller For:ACP-1500 HMFS 70	
Mechanical Seal For:ACP-1500 HMFS 70	
ACP-1500 HMFS 70, obsolete/replacement ACP-1800HMFS 70	
AR-99-00528	
T.P.ACP-900HMFS45	
ATP-216HA	
ATP-212HA (5135000)	
ACP-3700 MFC200H obsolete, replacement ACP-4000HMFD	
ACP-4000HMFD200V	
ATP-206HA	
ACP-2200 HMFS 100	
ACP-2500HMFS100	
ACP-1500HMFS1500 - NO LONGER AVAILABLE	
ACP-1800HMFS70	
ACP-2500HMFS85	
ACP - 2500HMFS100	
5135000	
ACP-3700 obsolete, replacement ACP-4000HMFD200V	
ACP 3700 HMFS 145 obsolete, replaced by ACP4000HMFS145	
ACP-4000HMFS145	
ACP3700HMFS145,obsolete replaced by ACP4000HMFS145	
ACP-1500HMFS 70 obsolete,replaced by ACP-1800HMFS70	
ACP-900 HMFS45	
ACP-1500 HMFS70 obsolete,replaced by ACP-1800HMFS70	
ACP-1100HMFS45	
ACP-1800HMFS70 (5161790)	

Urün	Tarif
5136360	
ACP-3700HMFS145-390 obsolete, replacement ACP-4000HMFS145	
AMGP-01NS-220	
ACP-750HF 19 -NO LONGER AVAILABLE	
ACP-600HF28	
ACP-600HF18	
ARD-345-33333	
ACP-101A	
P/n.5161760 Type T.P.ACP-1100HMFS45 30L/3Bar	
HCP-1100MF- alternative ACP-1100MF 220/380V	
ACP-1100MF 220/380V	
AMGP-01AF-T03	
ACP-4000HMFD200H	
ACP-1800HMFS70	
AMTP-216HA(VB)	
AMTP-1500-216HAVBF	
MECHANICAL SEAL FOR PUMP ACRK 2-150/15	
AMTP-3M-750-220HA	
ACP-900MF	
ACP-1800MF	
ACP 1500 MFS Obsolete!! Replaced by ACP-1800MF	
AMGP-01SF 110V	
ACP-4000HMFD200V	
ACP4000HMFD200V	
ACP-1800HMFS70K obsolete, replacement ACP-1800HMFS70	
ACP-4000HMFD part number incomplete	
ACP-1800 HMF	
AMTP-400V-206HA(VB)	
Motor for AMTP-400V-206HA(VB)	
T-Rotor 206 HWM	
Motor For T-Rotor 206 HWM	
5134800 (Pumpenmotor T-Rotor 400W)	
ATP-320HVB	
Pumpenmotor T-Rotor 1500W 2HP	
AMTP-400-204HA-VB 1.5	
5134800	
5135040	
5100400	
AGP-15C-CT 220V	
AGP700, 700cc (grease)	
AMTP-200-13MSVB	
ACP 1500 HMSF 70	
ARC-12FC	
ACRK 16-50/2	
ATP-216CHVD-30	
ATP-216HA(VB) check item ATP-216HA	
AMGP-01 AF	
ACP-1500HMFS70 obsolete, replacement ACP-1800HMFS70	
ACHK 2-40/4	

Ürün	Tarif
ARV-4SS	
1010670	
5134800	
Pumpenmotor T-Rotor 400W	
ATP-212HA (5135000)	
ACP-250F (5136350)	
ACP-3700HMFS-145-B	
AMTP-216CH-30 see AMTP-3000-216CHVD-30	
AMTP-3000-216CHVD-30	
ACP-1500 HMF 70	
AMGP-01AF-T03-T 110	
ACP - 3700	
AMGP-01AF-T03-T-110	
Gleitringdichtung für ACP 1500	
ACP400HMFS-WH	
AMTP-1500-220HAVBF	
seal kit for ACRK4-160/16	
5142320	
Gasket for ACP-1100HMFS45 (not sold separately)	
O-Ring for ACP-1100HMFS45 (not sold separately)	
T.P.ACP-1100HMFS45	
AMGP-01MF, 110V	
motor fan cover for CHX-60/6	
AMGP-01MF, 220V	
ACP - 1500HMFS700	
HAVBF 100MESH	
Repair kit for ACP-2200 HMFS 100	
ACRK 2-150/15 / alternative ACRK 2-130/13	
ACRK 2-130/13	
TD-4	
ACP-4000MF	
17030304	
ACP-4000 HMFC200V-390	
AMGP-025NS-T12-TY	
Coupling for AMTP-216HAVD	
ARD-345-44444	
ARD-342-44	
ARD-343-444	
ACPQ-300HSP-200	
ACP-400HF18	
5134800	
5135030	
5134800	
ACP-1500	
AMTP-216LNVT	
AMGP-01SF-200	
ATP-216HA	
MCP 3700 MFC 200 H wrong code	
AMGP-3M2-01N-T03-TY	

Ürün	Tarif
AMGP-01NS	
5232690	
5240130	
5135070	
ATP-206HA (5135030)	
MGP-200NS-T03-220 (5212630)	
ATP-216HA	
ARU-6	
AMTP-216HAVD	
AR-3S	
OHMFS 70	
ACP-180HF18 (5233720)	
ACP-60F	
ARD-343-111 (5195120)	